MARYLAND HISTORICAL TRUST ABRIDGED INVENTORY FORM INTERCOUNTY CONNECTOR PROJECT

Property Name: Calverton BPO Elks Property Survey No.: PACS E1.22

	,
Resource Summary: Property Address 4343 Sandy Spring Road, Burtonsville, M	M: 34-45
Historic/Current Function dwelling/dwelling	Year Built <u>1927</u>
Property is not individually eligible for National Register bed	cause:
It is less than 50 years old and does not meet N.R. exception G _x_It is an undistinguished example of a common building type or architectural style	 x Its integrity is compromised by alterations or deterioration x Its historic setting has been compromised by development Other (explain):
.	

Description:

The Calverton BPO Elks Property is a 1½-story, 3-bay side gable cottage on the southwest side of Sandy Spring Road in Burtonsville, Montgomery County. Constructed in 1927, the building has a rear addition and exhibits features of the bungalow style.

The structure has an asphalt shingle, side gable roof, with a shed dormer, and an exterior chimney on the southwest facade. It is of concrete masonry construction with brick veneer, and it has a concrete masonry foundation. The windows are double-hung wood sash. The house has an integrated, extended roof porch on the north elevation. The porch is enclosed with brick and has five arched openings: three on the northeast facade and one each on the northwest and southeast facade. The porch has a concrete floor and concrete steps.

The Burtonsville Elks Lodge is located on this property. The Lodge is a concrete masonry meeting house with a gambrel roof covered with asphalt shingles. The Lodge was constructed in 1976, and it is located immediately southwest of the house.

There is also an outbuilding associated with the property. This outbuilding is a shed with a standing seam metal, shed roof. Constructed circa 1975, it is of wood frame construction. The structure is located south of the house and southeast of the Elks Lodge.

The property is located on the south side of Sandy Spring Road, with residential property to the east, south and west. There are a few old trees, and the property is level. The property's setting is suburban, with heavily travelled Sandy Spring Road approximately 150 feet to the northeast.

MHT CONCURRENCE: EligibilityRecommended CriterlaABCD ConsiderationsABC Comments:	DEFGNone	
Reviewer, Office of Preservation Services Date	Reviewer, NR Program	7 27 9V Date

Preparer: P.A.C. Spero & Company


October 1996

Of red

Property Name: Calverton BPO Elks Property Survey No.: PACS E1.22

Resource Sketch Map

M: 34-45



Preparer:
P.A.C. Spero & Company
October 1996





1 28 M:34-45 2 8 A Ell Higherty 3. Mortgonery anny 4 Ryan Mc Kay 9 February 1996 6 PAC Spens and Congany, Tawson AD 21204 1 9747 Jurdy Jong Road northeast Parade 8/0/4



2 BHO (1) & Hoperty 3 Montgomery County 4 Ryan McKay 5 February 1996 6 PAC Spero and Company Tauson MD 21204 7 4343 Janly Spring Road, northwest and 8294



1 2xcs M: 34-45 2 10 Che Regenty 3 Mantgomery Courty 4 Ryan McKay 5 February 1996 6 PAC Spen and Company, Tawan MD 21207 74343 Pandy Joing Road, Southwest and sautheast facades 8394



1) PAGE 134-45 2 BPC El Stronery 3) Montgomery County 45 Fyon Yellow b) Telvucay 1990 6) PAC SPERO & COMPANY, TOWSON, MD 21204 14343 Sandy Spring POAD, ELKS LODGE 8,1014